

BULLETIN #: **TB208**

DATE:

**April 30, 2015**

CATEGORY:

**In-Floor Cleaning**

SUBJECT:

**Caretaker New 8-Port Tee***Product Update*

# CARETAKER<sup>™</sup>

## New 8-Port Tee and Teflon-Encapsulated Tee

Caretaker has improved the tee in the 8-port valve. The front of the tee contains a new sleeve that is made out of low-friction polymer to reduce binding inside the valve. The top of the tee includes a new Teflon-encapsulated O-ring that reduces friction and wear, and creates a better seal to prevent water leakage. The new tee and O-ring are currently shipping on all 8-port systems and replacement parts (part numbers 5-7-300, 4-7-300, and 3-7-625).

- Reduces friction and binding
- New Teflon-encapsulated O-Ring
- Same part number and warranty
- Now shipping on all new systems and parts



For more information contact Caretaker at 855-280-6465 or [caretaker.custsupport@zodiac.com](mailto:caretaker.custsupport@zodiac.com).